



Type Vibra




Type Briab







C-C 980




C-C 1050







C-C 1100




C-C 1200










2x Momentsekvens
2x Moment sequences


ATTENTION!

Retighten bolted joints after
1000km








OBS!!

Efterdra bultarna vid
1000km







	<p>12x 24-016-120-2 M16x120 277 Nm 10,9</p>	
	<p>8x 24-016-130-2 M16x130 277 Nm 10,9</p>	
	<p>M30 725 Nm</p>	
	<p>M24 500 Nm</p>	